
## ACP-4320/ACP-2320 SATA driver bay installation Note

When user installs SATA driver bay into ACP-4320/ACP-2320, kindly refer below picture to install it. The wide side of FAN module needs to be installed near SATA connector



If customer installs wrong side of FAN module, mechanism conflict issue between SATA driver bay and AIMB Main board would occur.

