

PCM-9375 User Note Addendum

Please insert into Appendix A of PCM-9375 User Manual page 65.

1.1 Inverter Power (CN5) Original (wrong)

Table 1.1: Inverter Power (CN5)				
Part Number		1655305020		
Desc	ription	Wafer box 2.0mm 5P 180D Male w/Lock		
Pin	Pin Name		Signal Type	
1	+5 V		PWR	
2	GND		GND	
3	ENAB	K L	OUT	
4	VBR		OD	
5	VCC		PWR	

1.2 Inverter Power (CN5) New (correct)

Table 1.2: Inverter Power (CN5)				
Part	Number	1655305020		
Desc	ription	Wafer box 2.0mm 5P 180D Male w/Lock		
Pin	Pin Nam	e Signal Type		
1	+12 V	PWR		
2	GND	GND		
3	ENABKI	OUT		
4	VBR	OD		
5	+5V	PWR		

1

PN:2006937521 Date: 2006/8/01



Chapter 6 Ethernet Interface

Please insert into Chapter 6 of PCM-9375 User Manual page 52. The Ethernet Driver Installation using Intel's Chipset is illustrated. The following are new updated sections.

6.1.1 Ethernet Chipset: Realtek RTL8100

Win2000 OS: PCM-9375 does NOT support Win2000 OS.

Win XP/ WinCE / Win XPe OS: With LX800 Ethernet driver is auto-detected for WinXP/ Win CE and Win XPe.

6.1.2 Ethernet Chipset: Intel 82551ER

Win2000 OS: PCM-9375 does NOT support Win2000 OS.

WinXP / WinCE / Win XPe OS: Ethernet driver needs to be installed when you use Intel 82551ER. The driver file is included in PCM-9375 driver CD.